

# Ravi Kumar Enterprises

## **CONSULTING CIVIL ENGINEERS & CONTRACTORS**

Govt. Approved Designers, Structural Engineers & Valuers in GVMC & VUDA

### **BUILDING STABILITY CERTIFICATE**

Name of the School : Timpany Senior Secondary School

Village, Town & District in which  
School is situated : D. No. 9-23-8, C.B.M. Compound,  
Visakhapatnam.


No. of floors on which the schools  
Classes are : It is a R.C.C Framed Structure with 3 Blocks.  
A - (G + 3) floors  
B - (G + 3) floors  
C - (G + 2) floors

Educational Dept.

Approval No. : CBSE/Aff./130146/(EX-01073-1516)/2015

I certify that I have inspected the School building on 14-07-2018 referred to above and examined the various parts including the foundations with special referred to the class rooms. I am of the opinion that the buildings are in accordance with the plans. These buildings are structurally sound and their stability will not be endangered by their use as School.

Date: 16-07-2018

  
K. RAVI KUMAR  
M. Tech (Structures)  
Licenced Engineer, Valuer  
GVMC / VUDA Licence No. 4187  
Ramnagar, Opp. GVMC Out Gate  
Visakhapatnam  
Ph: 92466 22291, Fax: 0891-2542724